



TDK Corporation

HHM1715E1

Sashe na Kari:

HHM1715E1

Manufacturer / Brand:

TDK Corporation

Bayanin samfur

BALUN 3.3GHZ-3.9GHZ 50/100 0603

Datasheets:

 [HHM1715E1.pdf](#)

RoHS Status

 Kira kyauta / RoHS mai yarda

Ship Daga

Hong Kong


Shipment Way

DHL/Fedex/TNT/UPS/EMS

NEMAN ZANCE

Hoton hoto na iya zama wakilci. Duba cikakkun bayanai don samfuriin samfuriin.













Bayani na HHM1715E1

SASHE NA KARI	HHM1715E1
MANUFACTURER	TDK Corporation
BAYANI	BALUN 3.3GHZ-3.9GHZ 50/100 0603
MATSAYIN FARKO / MATSAYIN ROHS	Kira kyauta / RoHS mai yarda
TAKARDAR BAYANAI	 HHM1715E1.pdf
SAUTI	HHM
KOMA LOSS (MIN)	10dB
BAMBANCIN MATAKAN	180° ±15°
PACKAGING	Cut Tape (CT)
PACKAGE / CASE	0603 (1608 Metric)
SAURAN SUNAYE	445-3995-1
NAU'IN SANYA	Surface Mount
SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MA'AIKACI TSAWON GWANINTA	12 Weeks
MATSAYIN FARKO / MATSAYIN ROHS	Lead free / RoHS Compliant
KADDAMAR DA LOSS (MAX)	1.0dB
KUSKUREN - BA'A DA KYAU / DAIDAITACCE	50 / 100 Ohm
YANAYIN FREQUENCY	3.3GHz ~ 3.9GHz
BAYANIN DALLA-DALLA	RF Balun 3.3GHz ~ 3.9GHz 50 / 100 Ohm 0603 (1608 Metric)

Related Tags

TDK Corporation HHM1715E1	Mai Rarraba HHM1715E1	Mai ba da HHM1715E1
Farashin HHM1715E1	Hoto HHM1715E1	Hoton HHM1715E1
Bayanan Bayani na HHM1715E1	Bayanin HHM1715E1 Download	Bayanan HHM1715E1
Kasuwancin HHM1715E1	Sayi HHM1715E1	Sayi TDK Corporation HHM1715E1
TDK Corporation HHM1715E1	Mai ba da TDK Corporation	Mai Rarraba TDK Corporation
TDK Corporation HHM1715E1		

Abubuwan da suka shafi

 <p>HHM1727D1 Manufacturers: TDK Corporation Bayani: BALUN 3.3GHZ-3.9GHZ 50/50 0603 A stock: Out stock RFQ</p>	 <p>HHM17165A1 Manufacturers: TDK Corporation Bayani: BALUN 2.4GHZ-2.8GHZ 50/50 0603 A stock: Out stock RFQ</p>
 <p>HHM17166A1 Manufacturers: TDK Corporation Bayani: BALUN 1.9GHZ-2.3GHZ 50/50 0603 A stock: Out stock RFQ</p>	 <p>HHM17153A2 Manufacturers: TDK Corporation Bayani: BALUN 698MHZ-894MHZ 50/50 0603 A stock: Out stock RFQ</p>
 <p>HHM17168B1 Manufacturers: TDK Corporation Bayani: BALUN 3.4GHZ-3.8GHZ 50/50 0603 A stock: Out stock RFQ</p>	 <p>HHM17144A1 Manufacturers: TDK Corporation Bayani: BALUN 791MHZ-960MHZ 50/100 0603 A stock: Out stock RFQ</p>
 <p>HHM17146A1 Manufacturers: TDK Corporation Bayani: BALUN 1.92GHZ-2.17GHZ 50/50 0603 A stock: Out stock RFQ</p>	 <p>HHM17139B1 Manufacturers: TDK Corporation Bayani: BALUN 2.4GHZ-2.5GHZ 50/50 0603 A stock: Out stock RFQ</p>
 <p>HHM17152A1 Manufacturers: TDK Corporation Bayani: BALUN 698MHZ-894MHZ 50/100 0603 A stock: Out stock RFQ</p>	 <p>HHM1726N1 Manufacturers: TDK Corporation Bayani: BALUN 824MHZ-915MHZ 50/100 0603 A stock: Out stock RFQ</p>
 <p>HHM1726P1 Manufacturers: TDK Corporation Bayani: BALUN 880MHZ-960MHZ 50/100 0603 A stock: Out stock RFQ</p>	 <p>HHM17139B2 Manufacturers: TDK Corporation Bayani: BALUN 2.4GHZ-2.6GHZ 50/50 0603 A stock: Out stock RFQ</p>

