



SICK


DGS35-YK402048

Sashe na Kari:	DGS35-YK402048
Manufacturer / Brand:	SICK
Bayanin samfur	ROTARY ENCODR INCREMENT 2048PPR
Datasheets:	
Ship Daga	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS



Hoton hoto na iya zama wakilci. Duba cikakkun bayanai don samfuriin samfuriin.













Bayani na DGS35-YK402048

SASHE NA KARI	DGS35-YK402048
MANUFACTURER	SICK
BAYANI	ROTARY ENCODR INCREMENT 2048PPR
MATSAYIN FARKO / MATSAYIN ROHS	
TAKARDAR BAYANAI	
VOLTAGE - BAYARWA	5V
YANAYIN KADDAMARWA	Connector
SAUTI	-
RAWAN ROTATIONAL (CYCLES MIN)	-
HATSARI TA JUYIN JUYA HALI	2048
KAYAN AIKI	-
SAURAN SUNAYE	1065096
GABATARWA	User Selectable
NAU'IN SANYA	Chassis Mount
MA'AIKACI TSAWON GWANINTA	3 Weeks
KODIN TSARIN RUBUTUN	Incremental
DETENT	No
GINA A CANJAWA	No
DOKAR MAI AIKI	Hole for Shaft

Related Tags

SICK DGS35-YK402048	Mai Rarraba DGS35-YK402048	Mai ba da DGS35-YK402048
Farashin DGS35-YK402048	Hoto DGS35-YK402048	Hoton DGS35-YK402048
Bayanan Bayani na DGS35-YK402048	Bayanin DGS35-YK402048 Download	Bayanan DGS35-YK402048
Kasuwancin DGS35-YK402048	Sayi DGS35-YK402048	Sayi SICK DGS35-YK402048
SICK DGS35-YK402048	Mai ba da SICK	Mai Rarraba SICK
SICK DGS35-YK402048		

Abubuwan da suka shafi

 <p>DGS35-YHK05000 Manufacturers: SICK Bayani: ROTARY ENCODR INCREMENT 5000PPR A stock: Out stock</p> <p>RFQ</p>	 <p>DGS35-YL202048 Manufacturers: SICK Bayani: ROTARY ENCODR INCREMENT 2048PPR A stock: Out stock</p> <p>RFQ</p>
 <p>DGS35-YK216384 Manufacturers: SICK Bayani: ROTARY ENCODR INCREMENT 16384PPR A stock: Out stock</p> <p>RFQ</p>	 <p>DGS35-YH401024 Manufacturers: SICK Bayani: ROTARY ENCODR INCREMENT 1024PPR A stock: Out stock</p> <p>RFQ</p>
 <p>DGS35-YKN16384 Manufacturers: SICK Bayani: ROTARY ENCODR INCREMENT 16384PPR A stock: Out stock</p> <p>RFQ</p>	 <p>DGS35-YL416384 Manufacturers: SICK Bayani: ROTARY ENCODR INCREMENT 16384PPR A stock: Out stock</p> <p>RFQ</p>
 <p>DGS35-YK201024 Manufacturers: SICK Bayani: ROTARY ENCODR INCREMENT 1024PPR A stock: Out stock</p> <p>RFQ</p>	 <p>DGS35-YKK16384 Manufacturers: SICK Bayani: ROTARY ENCODR INCREMENT 16384PPR A stock: Out stock</p> <p>RFQ</p>
 <p>DGS35-YKK02048 Manufacturers: SICK Bayani: ROTARY ENCODR INCREMENT 2048PPR A stock: Out stock</p> <p>RFQ</p>	 <p>DGS35-YK410000 Manufacturers: SICK Bayani: ROTARY ENCODR INCREMENT 10000PPR A stock: Out stock</p> <p>RFQ</p>
 <p>DGS35-YHK02500 Manufacturers: SICK Bayani: ROTARY ENCODR INCREMENT 2500PPR A stock: Out stock</p> <p>RFQ</p>	 <p>DGS35-YHN10000 Manufacturers: SICK Bayani: ROTARY ENCODR INCREMENT 10000PPR A stock: Out stock</p> <p>RFQ</p>

Hakkin mallaka © 2020 Dogara Mai Dogaro da Ma'aikatu Kayan Wuta - Ocean-Components.com

E-mail: Info@Ocean-Components.com

Adireshin: Room 2102, Connaught Commercial Building, 185 Wan Chai Rd, Wan Chai, Hong Kong

