



ADI (Analog Devices, Inc.)

AD9512BCPZ-REEL7

Sashe na Kari:

AD9512BCPZ-REEL7

Manufacturer / Brand:

ADI (Analog Devices, Inc.)

Bayanin samfur

IC CLK BUFFER 2:5 1.2GHZ 48LFCSP

Datasheets:

 AD9512BCPZ-REEL7.pdf

RoHS Status

 Kira kyauta / RoHS mai yarda

Ship Daga

Hong Kong


Shipment Way

DHL/Fedex/TNT/UPS/EMS

NEMAN ZANCE

Hoton hoto na iya zama wakilci. Duba cikakkun bayanai don samfurin samfurin.













Bayani na AD9512BCPZ-REEL7

SASHE NA KARI	AD9512BCPZ-REEL7
MANUFACTURER	ADI (Analog Devices, Inc.)
BAYANI	IC CLK BUFFER 2:5 1.2GHZ 48LFCSP
MATSAYIN FARKO / MATSAYIN ROHS	Kira kyauta / RoHS mai yarda
TAKARDAR BAYANAI	 AD9512BCPZ-REEL7.pdf
VOLTAGE - BAYARWA	3.135 V ~ 3.465 V
RUBUTA	Fanout Buffer (Distribution), Divider
ASUSUN NA'URA MAI BA DA KYAUTA	48-LFCSP-VQ (7x7)
SAUTI	-
RATIO - INPUT: OUTPUT	2:5
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	48-VFQFN Exposed Pad, CSP
KAYAN AIKI	CMOS, LVDS, LVPECL
SAURAN SUNAYE	AD9512BCPZ-REEL7-ND AD9512BCPZ-REEL7TR
TEMPERAYI MAI AIKI	-40°C ~ 85°C
YAWAN YANKUNA	1
NAU'IN SANYA	Surface Mount
SENSITIVITY LEVEL (MSL)	3 (168 Hours)
MA'AIKACI TSAWON GWANINTA	7 Weeks
MATSAYIN FARKO / MATSAYIN ROHS	Lead free / RoHS Compliant
INPUT	Clock
YANAYIN - MAX	1.2GHz
BAMBANCI - INPUT: KAYAN AIKI	Yes/Yes
BAYANIN DALLA-DALLA	Clock Fanout Buffer (Distribution), Divider IC 2:5 1.2GHz 48-VFQFN Exposed Pad, CSP
LAMBAR SASHIN SHAFIN	AD9512

Related Tags

ADI (Analog Devices, Inc.) AD9512BCPZ-REEL7	Mai Rarraba AD9512BCPZ-REEL7	Mai ba da AD9512BCPZ-REEL7
Farashin AD9512BCPZ-REEL7	Hoto AD9512BCPZ-REEL7	Hoton AD9512BCPZ-REEL7
Bayanan Bayani na AD9512BCPZ-REEL7	Bayanin AD9512BCPZ-REEL7 Download	Bayanan AD9512BCPZ-REEL7
Kasuwancin AD9512BCPZ-REEL7	Sayi AD9512BCPZ-REEL7	Sayi ADI (Analog Devices, Inc.) AD9512BCPZ-REEL7
ADI (Analog Devices, Inc.) AD9512BCPZ-REEL7	Mai ba da ADI (Analog Devices, Inc.)	Mai Rarraba ADI (Analog Devices, Inc.)
ADI (Analog Devices, Inc.) AD9512BCPZ-REEL7	AD AD9512BCPZ-REEL7	ADI (Analog Devices, Inc.) AD9512BCPZ-REEL7
Analog Devices Inc. AD9512BCPZ-REEL7	Analog Devices, Inc. AD9512BCPZ-REEL7	

Abubuwan da suka shafi

 <p>AD9511BCPZ Manufacturers: ADI (Analog Devices, Inc.) Bayani: IC CLK BUFFER 2:5 1.2GHZ 48LFCSP A stock: 136 pcs</p> <p>RFQ</p>	 <p>AD9513BCPZ Manufacturers: ADI (Analog Devices, Inc.) Bayani: IC CLK BUFFER 1:3 800MHZ 32LFCSP A stock: 343 pcs</p> <p>RFQ</p>
 <p>AD9510BCPZ-REEL7 Manufacturers: ADI (Analog Devices, Inc.) Bayani: IC CLK BUFFER 2:8 1.2GHZ 64LFCSP A stock: Out stock</p> <p>RFQ</p>	 <p>AD9512UCPZ-EP-R7 Manufacturers: ADI (Analog Devices, Inc.) Bayani: IC CLK BUFFER 1:5 1.2GHZ 48LFCSP A stock: Out stock</p> <p>RFQ</p>
 <p>AD9513/PCBZ Manufacturers: ADI (Analog Devices, Inc.) Bayani: BOARD EVAL FOR AD9513 A stock: 5 pcs</p> <p>RFQ</p>	 <p>AD9511BCPZ-REEL7 Manufacturers: ADI (Analog Devices, Inc.) Bayani: IC CLK BUFFER 2:5 1.2GHZ 48LFCSP A stock: Out stock</p> <p>RFQ</p>
 <p>AD9510BCPZ Manufacturers: ADI (Analog Devices, Inc.) Bayani: IC CLK BUFFER 2:8 1.2GHZ 64LFCSP A stock: 196 pcs</p> <p>RFQ</p>	 <p>AD9512UCPZ-EP Manufacturers: ADI (Analog Devices, Inc.) Bayani: IC CLK BUFFER 1:5 1.2GHZ 48LFCSP A stock: Out stock</p> <p>RFQ</p>
 <p>AD9514/PCBZ Manufacturers: ADI (Analog Devices, Inc.) Bayani: BOARD EVAL CLOCK 3CH AD9514 A stock: Out stock</p> <p>RFQ</p>	 <p>AD9512BCPZ Manufacturers: ADI (Analog Devices, Inc.) Bayani: IC CLK BUFFER 2:5 1.2GHZ 48LFCSP A stock: 155 pcs</p> <p>RFQ</p>
 <p>AD9513BCPZ-REEL7 Manufacturers: ADI (Analog Devices, Inc.) Bayani: IC CLK BUFFER 1:3 800MHZ 32LFCSP A stock: Out stock</p> <p>RFQ</p>	 <p>AD9512/PCBZ Manufacturers: ADI (Analog Devices, Inc.) Bayani: BOARD EVAL FOR AD9512 A stock: Out stock</p> <p>RFQ</p>