



SICK


**DBS50E-S5AK01024**

Sashe na Kari:	DBS50E-S5AK01024
Manufacturer / Brand:	SICK
Bayanin samfur	ROTARY ENCODR INCREMENT 1024PPR
Datasheets:	
Ship Daga	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS



Hoton hoto na iya zama wakilci. Duba cikakkun bayanai don samfuriin samfuriin.












**Bayani na DBS50E-S5AK01024**

SASHE NA KARI	DBS50E-S5AK01024
MANUFACTURER	SICK
BAYANI	ROTARY ENCODR INCREMENT 1024PPR
MATSAYIN FARKO / MATSAYIN ROHS	
TAKARDAR BAYANAI	
VOLTAGE - BAYARWA	4.5 V ~ 5.5 V
YANAYIN KADDAMARWA	Cable
SAUTI	-
RAWAN ROTATIONAL (CYCLES MIN)	2B
HATSARI TA JUYIN JUYA HALI	1024
KAYAN AIKI	-
SAURAN SUNAYE	1060689
GABATARWA	User Selectable
NAU'IN SANYA	Chassis Mount
MA'AIKACI TSAWON GWANINTA	3 Weeks
KODIN TSARIN RUBUTUN	Incremental
DETENT	No
GINA A CANJAWA	No
DOKAR MAI AIKI	Shaft

**Related Tags**

SICK DBS50E-S5AK01024	Mai Rarraba DBS50E-S5AK01024	Mai ba da DBS50E-S5AK01024
Farashin DBS50E-S5AK01024	Hoto DBS50E-S5AK01024	Hoton DBS50E-S5AK01024
Bayanan Bayani na DBS50E-S5AK01024	Bayanin DBS50E-S5AK01024 Download	Bayanan DBS50E-S5AK01024
Kasuwancin DBS50E-S5AK01024	Sayi DBS50E-S5AK01024	Sayi SICK DBS50E-S5AK01024
SICK DBS50E-S5AK01024	Mai ba da SICK	Mai Rarraba SICK
SICK DBS50E-S5AK01024		

**Abubuwan da suka shafi**

 <p><b>DBS50E-S5AK01200</b> Manufacturers: SICK Bayani: ROTARY ENCODR INCREMENT 1200PPR A stock: Out stock</p> <p><b>RFQ</b></p>	 <p><b>DBS50E-S5AK00400</b> Manufacturers: SICK Bayani: ROTARY ENCODR INCREMENTAL 400PPR A stock: Out stock</p> <p><b>RFQ</b></p>
 <p><b>DBS50E-S5AK01000</b> Manufacturers: SICK Bayani: ROTARY ENCODR INCREMENT 1000PPR A stock: Out stock</p> <p><b>RFQ</b></p>	 <p><b>DBS50E-S5AK02048</b> Manufacturers: SICK Bayani: ROTARY ENCODR INCREMENT 2048PPR A stock: Out stock</p> <p><b>RFQ</b></p>
 <p><b>DBS50E-S5AJ02500</b> Manufacturers: SICK Bayani: ROTARY ENCODR INCREMENT 2500PPR A stock: Out stock</p> <p><b>RFQ</b></p>	 <p><b>DBS50E-S5AK00100</b> Manufacturers: SICK Bayani: ROTARY ENCODR INCREMENTAL 100PPR A stock: Out stock</p> <p><b>RFQ</b></p>
 <p><b>DBS50E-S5AP01000</b> Manufacturers: SICK Bayani: ROTARY ENCODR INCREMENT 1000PPR A stock: Out stock</p> <p><b>RFQ</b></p>	 <p><b>DBS50E-S5AK00500</b> Manufacturers: SICK Bayani: ROTARY ENCODR INCREMENTAL 500PPR A stock: Out stock</p> <p><b>RFQ</b></p>
 <p><b>DBS50E-S5AK00360</b> Manufacturers: SICK Bayani: ROTARY ENCODR INCREMENTAL 360PPR A stock: Out stock</p> <p><b>RFQ</b></p>	 <p><b>DBS50E-S5AP02500</b> Manufacturers: SICK Bayani: ROTARY ENCODR INCREMENT 2500PPR A stock: Out stock</p> <p><b>RFQ</b></p>
 <p><b>DBS50E-S5CK02048</b> Manufacturers: SICK Bayani: ROTARY ENCODR INCREMENT 2048PPR A stock: Out stock</p> <p><b>RFQ</b></p>	 <p><b>DBS50E-S5AL0100</b> Manufacturers: SICK Bayani: ROTARY ENCODR INCREMENT 1000PPR A stock: Out stock</p> <p><b>RFQ</b></p>