



ADI (Analog Devices, Inc.)

AD9508BCPZ-REEL7

Sashe na Kari:

AD9508BCPZ-REEL7

Manufacturer / Brand:

ADI (Analog Devices, Inc.)

Bayanin samfur

IC CLK BUFF 1:4 1.65GHZ 24LFCSP

Datasheets:

 AD9508BCPZ-REEL7.pdf

RoHS Status

 Kira kyauta / RoHS mai yarda

Ship Daga

Hong Kong

Shipment Way

DHL/Fedex/TNT/UPS/EMS




AHEAD OF WHAT'S POSSIBLE™

NEMAN ZANCE

Hoton hoto na iya zama wakilci. Duba cikakkun bayanai don samfurin samfurin.













Bayani na AD9508BCPZ-REEL7

SASHE NA KARI	AD9508BCPZ-REEL7
MANUFACTURER	ADI (Analog Devices, Inc.)
BAYANI	IC CLK BUFF 1:4 1.65GHZ 24LFCSP
MATSAYIN FARKO / MATSAYIN ROHS	Kira kyauta / RoHS mai yarda
TAKARDAR BAYANAI	 AD9508BCPZ-REEL7.pdf
VOLTAGE - BAYARWA	2.375 V ~ 3.465 V
RUBUTA	Fanout Buffer (Distribution), Divider
ASUSUN NA'URA MAI BA DA KYAUTA	24-LFCSP-WQ (4x4)
SAUTI	-
RATIO - INPUT: OUTPUT	1:4
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	24-WFQFN Exposed Pad, CSP
KAYAN AIKI	CMOS, HSTL, LVDS
SAURAN SUNAYE	AD9508BCPZ-REEL7-ND AD9508BCPZ-REEL7TR
TEMPERAYI MAI AIKI	-40°C ~ 85°C
YAWAN YANKUNA	1
NAU'IN SANYA	Surface Mount
SENSITIVITY LEVEL (MSL)	3 (168 Hours)
MA'AIKACI TSAWON GWANINTA	7 Weeks
MATSAYIN FARKO / MATSAYIN ROHS	Lead free / RoHS Compliant
INPUT	CMOS
YANAYIN - MAX	1.65GHz
BAMBANCI - INPUT: KAYAN AIKI	Yes/Yes
BAYANIN DALLA-DALLA	Clock Fanout Buffer (Distribution), Divider IC 1:4 1.65GHz 24-WFQFN Exposed Pad, CSP
LAMBAR SASHIN SHAFIN	AD9508

Related Tags

ADI (Analog Devices, Inc.) AD9508BCPZ-REEL7	Mai Rarraba AD9508BCPZ-REEL7	Mai ba da AD9508BCPZ-REEL7
Farashin AD9508BCPZ-REEL7	Hoto AD9508BCPZ-REEL7	Hoton AD9508BCPZ-REEL7
Bayanan Bayani na AD9508BCPZ-REEL7	Bayanin AD9508BCPZ-REEL7 Download	Bayanan AD9508BCPZ-REEL7
Kasuwancin AD9508BCPZ-REEL7	Sayi AD9508BCPZ-REEL7	Sayi ADI (Analog Devices, Inc.) AD9508BCPZ-REEL7
ADI (Analog Devices, Inc.) AD9508BCPZ-REEL7	Mai ba da ADI (Analog Devices, Inc.)	Mai Rarraba ADI (Analog Devices, Inc.)
ADI (Analog Devices, Inc.) AD9508BCPZ-REEL7	AD AD9508BCPZ-REEL7	ADI (Analog Devices, Inc.) AD9508BCPZ-REEL7
Analog Devices Inc. AD9508BCPZ-REEL7	Analog Devices, Inc. AD9508BCPZ-REEL7	

Abubuwan da suka shafi

 <p>AD9510-VC0/PCBZ Manufacturers: ADI (Analog Devices, Inc.) Bayani: BOARD EVALUATION FOR AD9510 A stock: Out stock</p> <p>RFQ</p>	 <p>AD9508/PCBZ Manufacturers: ADI (Analog Devices, Inc.) Bayani: BOARD EVAL FOR AD9508 A stock: 4 pcs</p> <p>RFQ</p>
 <p>AD9484BCPZRL7-500 Manufacturers: ADI (Analog Devices, Inc.) Bayani: IC ADC 8BIT 500MSPS 56LFCSP A stock: Out stock</p> <p>RFQ</p>	 <p>AD9508SCPZ-EP Manufacturers: ADI (Analog Devices, Inc.) Bayani: IC CLK BUFF 1:4 1.65GHZ 24LFCSP A stock: 56 pcs</p> <p>RFQ</p>
 <p>AD9508BCPZ Manufacturers: ADI (Analog Devices, Inc.) Bayani: IC CLK BUFF 1:4 1.65GHZ 24LFCSP A stock: 604 pcs</p> <p>RFQ</p>	 <p>AD9510BCPZ-REEL7 Manufacturers: ADI (Analog Devices, Inc.) Bayani: IC CLK BUFFER 2:8 1.2GHZ 64LFCSP A stock: Out stock</p> <p>RFQ</p>
 <p>AD9510BCPZ Manufacturers: ADI (Analog Devices, Inc.) Bayani: IC CLK BUFFER 2:8 1.2GHZ 64LFCSP A stock: 196 pcs</p> <p>RFQ</p>	 <p>AD9508SCPZ-EP-R7 Manufacturers: ADI (Analog Devices, Inc.) Bayani: IC CLK BUFF 1:4 1.65GHZ 24LFCSP A stock: Out stock</p> <p>RFQ</p>
 <p>AD9510/PCBZ Manufacturers: ADI (Analog Devices, Inc.) Bayani: BOARD EVALUATION FOR AD9510 A stock: 2 pcs</p> <p>RFQ</p>	 <p>AD9484-500EBZ Manufacturers: ADI (Analog Devices, Inc.) Bayani: BOARD EVAL W/AD9484BCPZ-500 A stock: Out stock</p> <p>RFQ</p>
 <p>AD9484BCPZ-500 Manufacturers: ADI (Analog Devices, Inc.) Bayani: IC ADC 8BIT 500MSPS 56LFCSP A stock: 18 pcs</p> <p>RFQ</p>	 <p>AD9500WAFER Manufacturers: ADI (Analog Devices, Inc.) Bayani: IC ADC A stock: Out stock</p> <p>RFQ</p>