

N/A

CDCV850DGGRG4

Sashe na Kari: CDCV850DGGRG4
 Manufacturer / Brand: N/A
 Bayanin samfur: IC PLL CLOCK DRVR 2.5V 48TSSOP
 Datasheets:
 RoHS Status: Kira kyauta / RoHS mai yarda
 Ship Daga: Hong Kong
 Shipment Way: DHL/Fedex/TNT/UPS/EMS



NEMAN ZANCE

Hoton hoto na iya zama wakilci. Duba cikakkun bayanai don samfurin samfurin.

Bayani na CDCV850DGGRG4

SASHE NA KARI	CDCV850DGGRG4
MANUFACTURER	N/A
BAYANI	IC PLL CLOCK DRVR 2.5V 48TSSOP
MATSAYIN FARKO / MATSAYIN ROHS	Kira kyauta / RoHS mai yarda
TAKARDAR BAYANAI	
VOLTAGE - BAYARWA	2.3 V ~ 2.7 V
RUBUTA	PLL Clock Driver
ASUSUN NA'URA MAI BA DA KYAUTA	48-TSSOP
SAUTI	-
RATIO - INPUT: OUTPUT	1:11
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	48-TFSOP (0.240", 6.10mm Width)
PLL	Yes with Bypass
KAYAN AIKI	SSTL-2
TEMPERAYI MAI AIKI	0°C ~ 85°C
YAWAN YANKUNA	1
NAU'IN SANYA	Surface Mount
SENSITIVITY LEVEL (MSL)	2 (1 Year)
MATSAYIN FARKO / MATSAYIN ROHS	Lead free / RoHS Compliant
INPUT	LVTTL, SSTL-2
YANAYIN - MAX	140MHz
DIVIDER / MULTIPLIER	No/No
BAMBANCI - INPUT: KAYAN AIKI	Yes/Yes
LAMBAR SASHIN SHAFIN	CDCV850

Related Tags

CDCV850DGGRG4	Mai Rarraba CDCV850DGGRG4	Mai ba da CDCV850DGGRG4
Farashin CDCV850DGGRG4	Hoto CDCV850DGGRG4	Hoton CDCV850DGGRG4
Bayanan Bayani na CDCV850DGGRG4	Bayanin CDCV850DGGRG4 Download	Bayanan CDCV850DGGRG4
Kasuwancin CDCV850DGGRG4	Sayi CDCV850DGGRG4	Sayi CDCV850DGGRG4
CDCV850DGGRG4	Mai ba da	Mai Rarraba

Abubuwan da suka shafi

<p>CDCV850DGGR Manufacturers: N/A Bayani: IC PLL CLOCK DRVR 2.5V 48-TSSOP A stock: 26517 pcs RFQ</p>	<p>CDCV304TPWREP Manufacturers: N/A Bayani: IC CLK BUFFER 1:4 200MHZ 8TSSOP A stock: 21714 pcs RFQ</p>
<p>CDCV304PWR Manufacturers: N/A Bayani: IC CLK BUFFER 1:4 200MHZ 8TSSOP A stock: 53713 pcs RFQ</p>	<p>CDCV850IDGGG4 Manufacturers: N/A Bayani: IC PLL CLOCK DRVR 2.5V 48TSSOP A stock: 14095 pcs RFQ</p>
<p>CDCV850IDGG Manufacturers: N/A Bayani: IC PLL CLOCK DRVR 2.5V 48-TSSOP A stock: 23791 pcs RFQ</p>	<p>CDCV850IDGGR Manufacturers: N/A Bayani: IC PLL CLOCK DRVR 2.5V 48TSSOP A stock: 4418 pcs RFQ</p>
<p>CDCV850DGGG4 Manufacturers: N/A Bayani: IC PLL CLOCK DRVR 2.5V 48TSSOP A stock: 19469 pcs RFQ</p>	<p>CDCV850IDGGRG4 Manufacturers: N/A Bayani: IC PLL CLOCK DRVR 2.5V 48TSSOP A stock: 4037 pcs RFQ</p>
<p>CDCV304PWRG4 Manufacturers: N/A Bayani: IC CLK BUFFER 1:4 200MHZ 8TSSOP A stock: 66794 pcs RFQ</p>	<p>CDCV855IPW Manufacturers: N/A Bayani: IC 1:4 DDR PLL CLK-DRVR 28-TSSOP A stock: 38134 pcs RFQ</p>
<p>CDCV850DGG Manufacturers: N/A Bayani: IC PLL CLOCK DRVR 2.5V 48-TSSOP A stock: 22414 pcs RFQ</p>	<p>CDCV855IPWG4 Manufacturers: N/A Bayani: IC PLL CLOCK DRVR 2.5V 28TSSOP A stock: 26506 pcs RFQ</p>